

Kinden Phils. Corporation

ELECTRICAL & MECHANICAL CONTRACTOR

26 September, 2002

Our Ref.: RCB/KPC 2002-24

SUMITOMO CORPORATION
LRT Line 2 Depot Site Office
Marcos Highway , Santolan
Pasig City

Attention : **MR. MAKOTO AWAKIHARA**
Project Manager

Thru : **Mr. N. Yamasaki**
Electrical Engineer

Subject : Actual direct hit by lightning strike.

Gentlemen :

Reference to the above captioned subject we would like to inform your good office that last night 25 September 2002 at around 7:20 PM there was a tremendous lightning storm occurred in the vicinity of LRT 2 Depot and one of our newly installed lightning protection system was directly hit by lightning . The said installation is located at Area 5 and on top of 30 meter pole which is identified as TL 10.


To further support that it was directly hit by lightning ,we checked the lightning event counter and it was properly registered in the lightning event counter.

Based on these concept our installed lightning protection system which is **ERITECH System 3000** is very effective and would provide continuous coverage and protection for our Depot Line 2 structures. Being an advanced lightning protection system based on latest lightning research and technology **ERITECH System 3000** is an efficient system and of very high quality.


For your information and future reference.


Thank you very much.

Very truly yours,
KINDEN PHILIPPINES CORPORATION


RHOEL CRUZ BARBOSA (PEE)
Construction Manager

5 Flr. ODC International Plaza, 219 Salcedo St., Legaspi Village, Makati City, Philippines
Phone : (632) 812-64-40
Fax : (632) 840-13-34


RECEIVED
DATE: 27 SEPT 02
9:20 AM


NOTED: **GORDON A. EDWARDS**
RE. DEPOT
27 SEPT. 2002